

UNITED STATES
DEPARTMENT OF LABOR

OSHA

English | Spanish

Find it in OSHA

Q

A TO Z INDEX

OSHA

WORKER

EMPLOYER

STANDARDS

ENFORCEMENT

CONSTRUCTION

TOPIC

NEWS/RESOURCES

DATA

TRAINING

Enforcement Programs

National Emphasis Programs

Local Emphasis Programs

Directives

Severe Violators

Inspection Detail

Case Status: CLOSED

Inspection: 1217789.015 - Progress Rail Welding Corporation

Inspection Information - Office: Englewood

Nr: 1217789.015

Report ID: 0830600

Open Date: 03/16/2017

Progress Rail Welding Corporation

2621 Lime Road

Pueblo, CO 81006

Union Status: NonUnion

SIC:

NAICS: 488210/Support Activities for Rail Transportation

Mailing: 2621 Lime Road, Pueblo, CO 81006

Inspection Type: Referral

Scope: Partial

Ownership: Private

Safety/Health: Safety

Advanced Notice: N

Close Conference: 03/16/2017

Close Case: 07/17/2017

Related Activity: Type

Referral

ID

1191944

Safety

Yes

Health

Case Status: CLOSED

Violation Summary						
	Serious	Willful	Repeat	Other	Unclass	Total
Initial Violations	2					2
Current Violations	1					1
Initial Penalty	\$18,108	\$0	\$0	\$0	\$0	\$18,108
Current Penalty	\$8,054	\$0	\$0	\$0	\$0	\$8,054
FTA Amount	\$0	\$0	\$0	\$0	\$0	\$0

Violation Items											
	#	ID	Type	Standard	Issuance	Abate	Curr\$	Init\$	Fta\$	Contest	LastEvent
	1.	01001	Serious	5A0001	05/15/2017	07/15/2017	\$8,054	\$9,054	\$0		I - Informal Settlement

Deleted	2.	01002	Serious	19100132 A	05/15/2017	06/09/2017	\$0	\$9,054	\$0		I - Informal Settlement
---------	----	--------------	---------	------------	------------	------------	-----	---------	-----	--	-------------------------

Accident Investigation Summary						
Summary Nr: 93953.015		Event: 03/14/2017		Employee Crushes Foot On Steel Moving Equipment		
At 6:30 p.m. on March 14, 2017, an employee entered a restricted area and was manually manipulating the leading edge of a rail into lead out stacker #5. As lead out stacker #5 was displaced by the leading edge of the rail, the employee slipped. His left foot slid underneath lead out stacker #5, which fell and crushed his foot. The employee sustained a fractured left foot and severe lacerations from heel to toe.						
Keywords: caught in, falling object, fracture, crushing						
	Inspection			Degree	Nature	Occupation
1	1217789.015			Hospitalized injury	Cut/Laceration	Machinists

UNITED STATES DEPARTMENT OF LABOR

Occupational Safety and Health Administration
200 Constitution Ave NW
Washington, DC 20210
☎ 800-321-6742 (OSHA)
TTY
www.OSHA.gov

FEDERAL GOVERNMENT

White House
Severe Storm and Flood Recovery Assistance
Disaster Recovery Assistance
DisasterAssistance.gov
USA.gov
No Fear Act Data
U.S. Office of Special Counsel

OCCUPATIONAL SAFETY AND HEALTH

Frequently Asked Questions
A - Z Index
Freedom of Information Act
Read the OSHA Newsletter
Subscribe to the OSHA Newsletter
OSHA Publications
Office of Inspector General

ABOUT THE SITE

Freedom of Information Act
Privacy & Security Statement
Disclaimers
Important Website Notices
Plug-Ins Used by DOL
Accessibility Statement